



Glow In The Dark


Glow Heat Transfer Vinyl is great for decorating garments that need extra visibility such as work uniforms for delivery drivers and security guards. Even when the lights go off your designs will still be visible. White appearance in the light and has a lime green glow in the dark.


RECOMMENDED FABRICS

- Cotton
- Polyester
- Cotton/Poly Blends

Due to the combination of fabrics, weaves, coatings and dyes used in the textile industry, we recommend testing the application before production.

APPLICATION

 10-15 seconds

 305° - 310° F

 Medium

 Warm

ACCESSORIES

- Weeder
- Kraft Paper Or Teflon Sheet

APPLICATION

1. Preheat your garment
2. Line up your transfer
3. Cover with Kraft Paper or Teflon Sheet
4. Apply for 10-15 seconds at 320° F with a firm pressure
5. Peel Cold

MULTI-COLOUR APPLICATION

1. Heat apply background for 2 seconds, peel warm
2. Heat apply foreground for 10-15 seconds, peel warm

CARE

- Turn your garment inside out
- Machine wash, using a mild detergent
- Do not use bleach
- Tumble dry on low or normal settings
- Do not iron directly onto this material



All technical information and recommendations are based on tests we believe to be reliable. However, we cannot guarantee performance conditions not under manufacturer's control. Before using, we recommend testing to determine suitability of the product for its intended use. The user assumes all risk and liability whatsoever in connection with the use of this product.